ECS Configuration Change Request

CCR No. 96-0982B	**Logged Date** 10/29/96	**Rev.** B	**Request Type** CCR

Priority Routine ☐ Urgent ☒ Emergency ☐	**Affected Release** A	**Change Class** II

Title (description) Update Data Management disk configuration at GSFC (DOC# 420-td-036-003)

Documents Affected	**Source Nos** (RID, NCR, Action Item, GSFC CCR, etc.) **or Tech Reference**

RTM Change ☐   **Start New Baseline** ☐

Problem
The current data Management subsystem disk configuration at GSFC does not allow for the failover of dynamic, non-sybase data.

Proposed Solution
The proposed solution would be to attach the 5x2, 3x2, and 5x2 RAIDs to DMGHW-GSFC-5 when failure occurs, all the strings are switched to DMGHW-GSFC-6.

Impact Analysis:

Organizations Affected:

	BOO ☐	Contracts ☐	ESO ☐	FOS ☐	M&O ☐
QA ☐	Rel. A ☒	Rel. B ☐	Rel. IR1 ☐	MRS ☐	SMO ☐	Subconts ☐
A.1 ☐	Other _____				

Cost: None ☒   Small ☐   Medium ☐   Large ☐
                                   (Not exceeding $100,000)   ($100,000 to $500,000)   (Over $500,000)

Schedule: None ☐   Other

Additional LOC _____   Man-Months _____

Materials

Originator David Marquette	David Marquette	10/31/96
	Signature	Date

Office Rel A Office Manager	Narayan Prasad	10/31/96
	Signature for Manager	Date

Disposition   Approved ☒   Approved w/Comment ☐   Forward ☐   Disapproved ☐

Comments:

CCB Chairperson	Narayan Prasad	10/31/96
	Signature	Date

CM01JU96   *ECS*